



Navigation Wiring Modifications

1998 740iL

- | | |
|-----------------|----------------------------|
| 1 - N/C | 7 - N/C (was purple/white) |
| 2 - White/Green | 8 - Gray/Red |
| 3 - Black/Brown | 9 - White/Yellow/Gray |
| 4 - Black/White | 10 - Black/White |
| 5 - White/Brown | 11 - Purple/Red |
| 6 - Brown (big) | 12 - Red/Green (big) |



- | | |
|-----------------------|--------------------------|
| 1 - N/C | 7 - N/C |
| 2 - White/Green | 8 - Gray/Red |
| 3 - Black/Brown | 9 - White/Yellow/Gray |
| 4 - Black/White (big) | 10 - Black/White (small) |
| 5 - White/Brown | 11 - Purple/Red |
| 6 - N/C | 12 - Red/Green (big) |



NOTES:

- 1) The purple/white wire (ignition sense) on the harness plug has no matching wire on the car connector. This wire was removed and connected to the other purple/white wires attached to the body next to the rear lights.